

## HOLLIS & ANTHONY TOMB – Church Monument

### Challenge

One of five listed tombs in the churchyard of St Mary's Church, Beaconsfield. The large square profiled tomb consists of inscribed panels to all sides with a brick core surmounted by a raised capstone. All had collapsed into the vault below.

### Solution

The sections were recorded, dismantled and put aside for re-assembly. A concrete H beam was designed and constructed to bridge the double vault and the tomb was re-erected in its original position. It then received a light conservation clean.

### Results

The monument has been saved from total loss and enjoys its position in an interesting churchyard.

Client: St Mary and All Saints Church,  
Beaconsfield

Structural Engineers: Stress UK,  
Advisor for structural repairs.



CLIVEDEN CONSERVATION WORKSHOP LTD

THE TENNIS COURTS, CLIVEDEN ESTATE, TAPLOW, MAIDENHEAD, BERKSHIRE SL60JA  
Telephone 01628 604721 Facsimile 01628 660379 Bath Office: 01761 420300